

# Annexure D

## BUILDING SAFETY CERTIFICATE

No: 1217

Dated: 25-11-2025

It is certified that the existing building **Sri Umamaheshwari International School** (name of the building or premises) at **Lingasugur**(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<b>Ground Floor, First Floor and Second floor</b>					

The building is owned/occupied by **.Sri Umamaheshwari International School ,Lingasugur** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Assistant executive Engineer** (Name of Department/Govt.) on **19.11.2025**(date of inspection) in the presence of **Mr.Vinaykumar Ganachari** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **24.11.2025** for a period of **1 years** in accordance with rule and subject to compliance of the specific conditions as appended.

1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned dept and immediate action should be taken.
2. Should Procure Fire Safety from Fire Dept their recommendations should be followed and updated regularly.
3. Original Documents of the Building should be kept safety.

Issued on **24.11.2025** at **Lingasugur** by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name of Officer:

Designation:

Name & Address of Department/Office:

ಶ್ರೀಮಹೇಶ್ವರಿ ಇನ್ಟರ್ನಾಷನಲ್ ಸ್ಕೂಲ್, ಲಿಂಗಸುಗುರು

ಬಿ.ಬಿ.ಪಯೋಗಿ ಇಲಾಖೆ, ಉಪ-ನಿರೀಕ್ಷಕ

ಲಿಂಗಸುಗುರು.





## Annexure D

### BUILDING SAFETY CERTIFICATE

No: 1217

Dated: 24-11-2025

It is certified that the existing building **Sri Umamaheshwari International School** (name of the building or premises) at **Lingasugur**(address) is having block(s)/Floor(s)as per details below:

Detail of Block(s)in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s)in the Block	<b>Ground Floor, First Floor and Second floor</b>					

The building is owned/occupied by **.Sri Umamaheshwari International School ,Lingasugur** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Assistant executive Engineer** (Name of Department/Govt.) on **19.11.2025**(date of inspection) in the presence of **Mr.Vinaykumar Ganachari** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **24.11.2025** for a period of **1 years** in accordance with rule and subject to compliance of the specific conditions as appended.

1. In future, if the building has any issues relating to any cracks, collapse and leakage of water it should be reported to concerned dept and immediate action should be taken.
2. Should Procure Fire Safety from Fire Dept their recommendations should be followed and updated regularly.
3. Original Documents of the Building should be kept safety.

Issued on **24.11.2025** at **Lingasugur** by PWD Dept.

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

SWORN TO BEFORE ME

*Basavaraj Dinnibhavi*  
NOTARY  
LINGASUGUR 584122

Sd/-

Designation: Assistant executive Engineer

Name & Address of Department/Office:  
Lingasugur

No. of Corrections *(see)*